

Site visit – Sky Valley Education Center 3/25/19, 8:15 am

Amanda Zych and Jeff Hutchison of Snohomish Health District met Devlin Piplic, Monroe Public Schools

Photos taken by Amanda Zych



1. Classroom #5 – HVAC unit



2. Classroom #5 - HVAC unit



3. Classroom #5 – Close up of bottom of HVAC unit



4. Classroom #5 - Another close-up of under HVAC unit

---






5. Classroom #11



6. Classroom #11 – HVAC unit



7. Classroom #11 - close-up of under HVAC unit



8: Classroom #11 – Faux wall separator




9: Classroom #11: Carpet under faux wall

---




10: Classroom #20 – HVAC unit





11. Classroom #20 – under HVAC unit

---



12: Heater in Annex hallway



13: Annex hallway – close-up of heater



14. Room between A and C




15. Room between A and C

---



16. Boy's Locker room






17. Boy's locker room - Black soot on ceiling

---



18. Girl's locker room



19. Girl's locker room - Black soot on ceiling

---



20: Transportation Shed




21. Transportation Shed – Inside



22. Transportation Shed – Old light ballasts in yellow plastic in drums





23. Transportation Shed – Old light ballasts in yellow plastic in drums – close-up



24. Transportation Shed – Lid